Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	spector(s): Perkins				26-Aug-20
Company/Owner:	Into	mountain Gas	Company	Unit/OPID:	8160
company/owner.	Inter	inountain Gas	Company	onity of ib.	0100
Inspection Type & Time (1	day)		Total In	spection Days:	1
Standard: Construction: 1 Training: (T)(D) Integrity Management: Incident:					
M/M: Follow-up: OQ: Damage Prevention: D&A:					
Inspection Summary					
A construction inspection was performed on Das-co and Track, contractors for Intermountain Gas Company.					
26 Aug 2020: (.5 Construction) Observed a Das-co crew installing ¾" main to 11685 W Alyxandra, Nampa Idaho. All procedures were followed. Typed up report. Areas observed during this project were: Excavating, line locating, plastic pipe joining, pressure testing, bedding/backfilling. 26 Aug 2020: (.5 Construction) Observed a Track Utilities crew installing 2" mains and 3/4" stubs at Midway and Lake Lowell intersection, Nampa, Idaho. Additionally a separate crew was doing the backfilling for a joint utilities trench to include 2" mains. All procedures were followed. Typed up report. Areas observed during this project were: Fusing, installing 2"-3/4" saddle tees and bedding/backfilling trenches.					
Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Pictures of Job tickets.					
Corrective Action Required:		Follow-up Req	uired: Yes		
Yes No	X	9/1		by (date):	
Inspector (Lead): Bruce Perkins	fir RIB	//-/1		8/26/2020	
Reviewer:	The state of the s	SIM H		Date:	
Darrin Ulmer	Mark	JOHN MI		27 Aug e	2020